

REPORT OF CHANNEL CONDITIONS < 100 FEET WIDE (ER 1130-2-3165)					PAGE 1 OF 1		
					DATE 6 March 2002		
TO: THE RECORD Commander, First Coast Guard District 408 Atlantic Ave. Boston ,MA 02110-2290				FROM: U.S. Army Corps of Engineers 26 Federal Plaza, ATTN: CENAN-OP-ST New York, NY 10278-0090			
RIVER/HARBOR NAME AND STATE: Patchogue River, Great South Bay, NY					MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT				80% OF CHANNEL WIDTH (feet)	
		WIDTH (feet)	LENGTH (miles)	DEPTH (feet)			
Entrance Channel	7/9-11/01	100	1.7	10		6.2	
10 ft Inside Section	7/9-11/01	100	.8	10		1.4	
8 ft Inside Section	7/9-11/01	100	.2	8		3.7	
REMARKS (Continue on reverse)							
1. All depths are in MLW. Controlling depths for the channel are based upon 80% of the channel width, 40% on each side of the channel centerline. 2. Entrance Channel: shoaling throughout the entire channel. 3. 10 ft Inside Section: shoaling throughout the entire section. 4. 8 ft Inside Section: shoaling throughout the last 200 ft of this section.							